



# Safety considerations when handling metal powders

Although the incidents are a compilation of all types of dusts, the number due to metal powders is a significant proportion. The Chemical Safety Board's report showed that (albeit for a limited number of cases) metal dust accounted for 20 per cent of all explosions.

An example of one such incident was at Hayes Lemmerz International-Huntington's aluminium foundry in October 2003, and this gives some perspective on the immensity of the hazard. Aluminium dust particles produced during the diecasting process were collected by a dust extraction system for recycling and were stored in a trap outside the factory. A spark ignited an initial explosion in this trap, which then rapidly spread along the extraction piping (containing dust deposits) into the plant. The shock waves caused additional dust to be released into the atmosphere in the plant and this then exploded and destroyed a major part of the factory. It was fortunate that only a few people were present at the time, as the death toll could have been very high—nevertheless one person died and six were injured. Figure 1 shows the damage to the foundry. The investigation report concluded that this was a preventable incident and was due to a combination of ignorance of the danger as well insufficient maintenance, inspection, and cleaning of the dust collection system<sup>6</sup>.

Apart from the risk of fire or explosion, powder particles can also have a serious impact on health, especially when inhaled. A concern is that the effects on the human body may



Figure 1—Aftermath of aluminium dust explosion at Hayes Lemmerz International-Huntington foundry<sup>6</sup>

take time to develop and the consequences of long-term exposure may be evident only many years later. In the case of nano-scale particles, absorption can also occur through the skin. How these particles impact on cell and organ function is not fully known, but effects range from mild irritation to auto-immune diseases and cancers<sup>7</sup>.

This paper will outline the hazards of metal powders in general but will also make specific reference to the metals of interest to this conference; namely, zirconium, tantalum, hafnium and niobium.

Although the emphasis is on powder metallurgy related activities, this information is also relevant for facilities using other metalworking operations (e.g. casting, grinding, machining, and welding) as these can generate a significant amount of dust deposits within a work area over time. A lack of awareness coupled with inappropriate cleaning methods (i.e. using compressed air) can create high-risk conditions.

## Fire and explosion

The conditions required for a fire or an explosion are shown schematically in Figure 2.

In the case of a fire, three components are needed: a fuel (powder), sufficient oxygen in the atmosphere, and a spark or other source of ignition.

An explosion on the other hand requires the powder be present as a dust cloud. The severity of the explosion can be increased if these elements are constrained within some form of enclosure. In this case the explosion may escalate from a deflagration (subsonic wavefront) to a detonation (supersonic wavefront).

A dust/powder explosion in a factory or facility typically occur in two stages: the first being the initial ignition and explosion of a quantity of powder. This is usually of limited size (depending on the amount of powder involved), with the damage to buildings and personnel being relatively low. However, the shock waves created by this can cause powder deposits within the facility (on ledges, beams, tops of equipment, on the floor etc.) to be released into the air and this provides a ready source of fuel for the initial flame front to consume, resulting in the second and far more devastating stage. This latter explosion or series of explosions can rapidly progress throughout the factory, with catastrophic consequences.

The powder particle size is an important factor, and it is generally considered that this must be less than 420 µm (i.e. will pass through an US #40 sieve) for an explosion to be




Figure 2—Schematic outline of the parameters for a fire or explosion (redrawn from reference<sup>8</sup>)

## Safety considerations when handling metal powders

initiated<sup>9</sup>. If the size is larger than 420  $\mu\text{m}$  the mass becomes sufficient to act as a heat sink and it will be difficult to cause ignition. However, once an explosion is in progression, larger particles will be readily consumed.

As would be expected, the composition of the powder particles is a strong determinant of the amount of energy released during an explosion. Figure 3 shows explosion test results for a range of materials under similar conditions.

Aluminium can be seen to be the most reactive, followed by magnesium.

Unfortunately similar data for Zr, Ta, Hf, and Nb could not be found. However, comparison of maximum combustion enthalpies (Figure 4) would suggest that zirconium is slightly less reactive than titanium<sup>11</sup>. Conversely, the flame speed is much faster than even aluminium (Figure 5), despite zirconium having a coarser particle size<sup>12</sup>.

Hafnium appears to be more reactive than both zirconium and titanium<sup>13</sup>, but less so than magnesium<sup>14</sup>.

Niobium is probably similar in reactivity to tantalum<sup>14</sup>.

### Powder characterization

Characterizing the powder that is being used is an important tool in understanding the potential fire or explosion risks. Various parameters have been explored in the literature, but the most important are the particle size range, the minimum explosion concentration, the minimum ignition energy, the minimum ignition temperature, the minimum auto-ignition temperature, and the dust deflagration index. Standard




Figure 3—Comparison of energy release during controlled explosion tests of different powders<sup>10</sup>




Figure 4—Comparison of combustion enthalpies of various materials<sup>11</sup>

methods for determining these values have been established<sup>12, 15–20</sup>. These parameters are discussed in the following sections.

### Particle size

As mentioned earlier, there is a practical guideline that states the maximum particle size that will initiate an explosion is 420  $\mu\text{m}$ . However as this size is reduced the reactivity increases markedly, and this is clearly shown in experimental work done on aluminium powder<sup>21,22</sup>.

Figure 6 indicates that as the average particle size decreases, the energy released (shown by the maximum rate of pressure rise) increases. A further factor is that less powder is required for a significant pressure rise to take place.

When the size is reduced further into the nanoscale range, there is a continued increase in the rate of pressure rise, but this then appears to reach a maximum value and subsequently decreases (Figure 7). The difficulty in measuring the actual effect of size in the nanometre range is the propensity for the particles to agglomerate, and this may be part of the reason for the decrease observed in Figure 7. Another reason may be the higher ratio of oxide to metal in the smaller particles, which would also reduce the reactivity.




Figure 5—Flame speeds for various powders as a function of dust concentration<sup>12</sup>. Median powder sizes: ~45  $\mu\text{m}$  (Zr), ~9  $\mu\text{m}$  (Al), ~50  $\mu\text{m}$  (Ti), ~45  $\mu\text{m}$  (Mg)




Figure 6—Effect of average aluminium powder size on the rate of pressure rise at different concentration levels<sup>21</sup>

# Safety considerations when handling metal powders




Figure 7—Effect of moving to nano-sized particles on pressure rise for aluminium powder<sup>22</sup>

As will be seen in the following sections, the powder particle size has a strong influence on all the other parameters.

### Minimum explosion concentration

The minimum explosion concentration (MEC) is defined as the smallest amount of dust suspended in air, under a specific set of test conditions<sup>16</sup>, that will initiate an explosion. It is also referred to as the lowest explosibility limit (LEL).

Data for a variety of metal powders is given in Table I. Significant variations in the minimum concentration




Figure 8—Effect of aluminium powder particle size on the minimum explosion concentration (redrawn from reference<sup>26</sup>)

limits are reported for the same metal. This can be due to a variety of reasons, e.g. different particle sizes, moisture levels, and degree of oxidation of the particles. The effect of particle size on the minimum concentration of aluminium can be seen in Figure 8.

### Minimum ignition energy

The minimum ignition energy (MIE) measures the ease of ignition of a dust cloud by electrical and electrostatic discharges. The test should be conducted under specific conditions that are detailed in the relevant standard<sup>17</sup>. MIE values for various metal powders are listed in Table II.

Two of the key factors that determine the ignition energy

Table I

Minimum explosion concentrations		
Powder	MEC (g.m <sup>-3</sup> )	Reference
Nb	? (Can be very low)	23
Nb	~ 420	24
Ta	160-165	23
Ta	~ 400	24
Hf	~ 180	24
Zr	45	23
Zr	40	25
Mg	328 (75 µm)	23
Al	45-170 (2-63 µm)	23
Ti	45	23

Table II

Minimum ignition energies		
Powder	MIE	Reference
Zr	1.8 – 18 µJ	27
Zr (<10 µm)	2-5 µJ	25
Zr	5 mJ	28
Zr	5-15 mJ	29
Zr	5 mJ	30
Ta	< 0.2 mJ (layer), 14-120 mJ (cloud)	31
Ta	120 mJ	29
Ta	< 3 mJ	23
Nb	< 3 mJ	23
Hf	? (≈ Ti?)	-
Al	3-13 mJ	23
Mg	20 mJ	28

## Safety considerations when handling metal powders




Figure 9—The dependence of the MIE of titanium on particle size and powder quantity (redrawn from reference<sup>32</sup>)

of a dust cloud are the particle size and the quantity of powder present. This is illustrated for the case of titanium in Figure 9, where sizes of 3 µm and less have a value of about 2 mJ. Large quantities of powder also have a significantly lower MIE.

### Minimum ignition and auto-ignition temperature

The minimum ignition temperature (MIT) is the lowest surface temperature capable of igniting a powder or dust dispersed in the form of a dust cloud. This is relevant for defining the maximum operating temperature for electrical and mechanical equipment used in dusty environments. Some metal powders, however, are capable of self-ignition (auto-ignition), and it is obviously important to know the lowest temperature at which this occurs.

Table III lists these values for the metals of interest.

Again, reducing the particle size will increase the reactivity of the powder and consequently lower the MIT. Data for aluminium is shown in Figure 10.




Figure 10—Influence of particle size on the MIT of aluminium<sup>40</sup>

### Dust deflagration index

The Deflagration Index (KSt) is essentially the maximum rate of pressure rise generated when dust is tested in a confined enclosure, and provides an estimate of the anticipated violence of a dust explosion.

The formula used to calculate this parameter is<sup>21</sup>:

$$K_{St} = (dP/dt)_{max} \times V^{1/3}$$

where  $(dP/dt)_{max}$  is the maximum rate of pressure rise (bar.s<sup>-1</sup>) and  $V$  is the volume of the testing chamber (m<sup>3</sup>). A 20-litre chamber is typically used as this gives comparable results to much larger chamber volumes that would occur in practice. However, these need to be geometrically similar for this index to be valid<sup>41</sup>.

The classification of explosion severity is according to the Table IV.

The dust deflagration index values for some metal powders are listed in Table V.

Table V shows some variation for particular metals and this could be due to a combination of factors that are known

Table III

### Minimum ignition temperatures

Powder	MIT (°C)	Reference
Zr	235 ± 65	33
Zr (10 µm)	May auto-ignite at room temperature	34
Zr (17.9 µm)	350	23
Zr	190 (layer)	23
Ta	300 (layer)	
	610-630 (cloud)	31
Ta	400-600 (cloud)	23
Ta	May auto-ignite at room temperature	35
Hf	190	36
Hf (10µm)	May auto-ignite at room temperature	37
Nb	5µm powder may auto-ignite at room temperature	38
Al	650 deg C (cloud); 760 deg C (layer) (aluminum, atomized); 610 deg C (cloud); 320-326 deg C (layer) (aluminum, flake); 420 deg C (aluminum, 6 µm)	39
Mg	560 (cloud)	23
Ti	332-587 (cloud)	
	382-510 (layer)	23
Ti	May auto-ignite at room temperature	23

# Safety considerations when handling metal powders

Table IV  
Rating of explosion severity according to the K<sub>st</sub> value<sup>23</sup>

Dust explosion class	K <sub>st</sub> (bar.m/s)	Characteristic
St 0	0	No explosion
St 1	>0 and <= 200	Weak explosion
St 2	>200 and <= 300	Strong explosion
St 3	> 300	Very strong explosion

Table V  
K<sub>st</sub> values for metal powders

Metal	K <sub>st</sub> (bar.m/s)	Reference
Zr	150	42
Ta	See Figures 11-12	42
Ta	90	43
Ta	~ 3 (2-30 μm)	14
Nb	~ 4 (10-60 μm)	44
Hf	>= 50 (4-30 μm)	14
Al	220 (5-15 μm)	14
Al	22 (20-100 μm)	14
Al	23-332 (2-63 μm)	23
Mg	53 (20-60 μm)	14
Ti	>= 40 (20-70 μm)	14
Ti	35 (10-60 μm)	44

to influence the index value: the size of the particles, the quantity of powder, moisture level, initial powder temperature, igniter energy, and degree of particle oxidation<sup>44</sup>. Considerable variations in results are also known to occur when different test method are used<sup>41</sup>.

The effects of dust concentration and particle size on the values for tantalum are shown in Figures 11-12. Clearly the amount of powder present and the particle size have a large impact on the severity of the explosion.

Reducing the particle size into the nanometre range appears to lower the K<sub>st</sub> value, as shown for aluminium (Figure 13). This may be due to the agglomeration effect that was noted earlier.




Figure 11—Dust deflagration index for tantalum as a function of the dust concentration<sup>31</sup>




Figure 12—Influence of tantalum particle size on the K<sub>st</sub> value<sup>31</sup>




Figure 13—Influence of particle size on the dust deflagration index of aluminium (data from<sup>21,22</sup>)

## Influence of moisture

The presence of moisture can increase the MIT, as shown for zirconium (Figure 14).

In view of this, safety guidelines for zirconium and hafnium stipulate that these powders should not be handled when dry or when the moisture content is less than 10-25 per cent by weight<sup>34,45</sup>.

## Influence of inert elements

The addition of an inert element or compound can significantly reduce the reactivity of a metal powder. This may not be a feasible option during the processing of powders, but could be a consideration when disposing of powder waste. As noted earlier, the oxidation of powder particles can cause an inerting effect, particularly when the particle size is small. Figures 15-16 show the effect of adding ZrO<sub>2</sub> to zirconium on the K<sub>st</sub> and MIT values.

A further example is for aluminium, where additions of sodium bicarbonate and monoammonium phosphate increase the MEC (Figure 17).

The characterization parameters that have been discussed are vitally important for assessing the risk of fire or explosion. However, reliance on data from the literature is

## Safety considerations when handling metal powders




Figure 14—Effect of moisture on the ignition temperature of zirconium powder<sup>42</sup>




Figure 16—Addition of ZrO<sub>2</sub> increases the MIT of Zr<sup>42</sup>




Figure 15—Effect of addition of ZrO<sub>2</sub> on the K<sub>st</sub> value of zirconium<sup>42</sup>




Figure 17—Inerting of aluminium powder<sup>46</sup>

not recommended as there can be considerable variance in the reported test values, as has been seen. Furthermore, there may be little correlation between laboratory test conditions and the actual situation in a facility or factory. It is therefore essential to conduct tests on the actual powder (or powder combinations) being processed as well as simulate, as closely as possible, the real environment that is experienced (i.e. temperature, humidity, turbulence etc) in the working area. Having realistic parameter values is obviously important when suitable venting and containment systems need to be designed.

### Health risks

Exposure to metal powders can have an impact on the health of personnel and is of particular concern when exposure is over a long term. However, understanding the influences of a particular powder on health is problematic, as individual sensitivities vary and predispositions for a particular illness can be triggered in one person while others are unaffected. Furthermore, personnel in industry are usually exposed to a multitude of dusts and other chemicals, and it may not be clear what has caused a particular effect.

Detailed toxicological investigations have not been conducted on all metal powders, and thus data is often limited to various ailments that have been reported for people working with that particular powder (amongst other things).

There are three ways that powders can interact with the body:

- Skin contact, which may lead to some form of irritation or allergic reaction (e.g. dermatitis). In the case of nano-powders, the particles can penetrate the skin and become absorbed into cells in various parts of the body, including the brain
- Eye contact, resulting in a mechanical irritation and cause damage
- Inhalation and either ingestion by swallowing or entering the lungs, resulting in possible breathing problems.

In the case of inhalation, the size of the particles determines the level of penetration into the lungs (Figure 18).

Nanometre sized particles are particularly concerning due to their ability to penetrate the skin and internal membranes, with the consequent potential to interfere with cellular activity. The realm of nanotechnology is still relatively new and it is too early to really know what the long-term effects will be. It appears that at this size range differences in powder composition may be of less importance, and that it is rather their presence as foreign objects in cells that causes the problem. However, more research needs to be done to understand the actual mechanisms involved. Nevertheless, there is some indication that nanoparticles (in general) can cause a variety of ailments, and this is summarized in Figure 19.

# Safety considerations when handling metal powders




Figure 18—The size of particles determines how much is inhaled and where they are deposited<sup>47</sup>

The following sections outline the known health aspects of the metal powders (in the micrometre scale) that are of interest to this conference.

## Zirconium

Zirconium has no known biological role, and zirconium compounds are of low toxicity. Short-term exposure to zirconium powder can cause irritation, but only contact with the eyes requires medical attention. Inhalation of zirconium

compounds can cause skin and lung granulomas. Zirconium aerosols can cause pulmonary granulomas<sup>49,50</sup>.

The exposure limits to dusts are usually specified in terms of a time-weighted average concentration for up to a 10-hour workday during a 40-hour workweek (TWA) and a short-term exposure limit (STEL). The values that have been set for zirconium are given in Table VI.

## Tantalum

This is generally not considered toxic however one report indicates tantalum may be a non-specific, surface carcinogen (based on animal studies)<sup>35,52</sup>.

Repeated or prolonged exposure to tantalum alloy dust may lead to mild fibrosis and chronic rhinitis, and it may also play a role in producing 'hard metal pneumoconiosis'. Irritations to the eyes and skin have been observed.

The exposure limits for the USA and other countries are shown in Table VII.

Agency	TWA (mg/m <sup>3</sup> )	STEL (mg/m <sup>3</sup> )
NIOSH	5	10
OSHA	5	

NIOSH: National Institute for Occupational Health and Safety (USA)  
OSHA: Occupational Safety and Health Administration




Figure 19—Collation of the recorded diseases attributed to nanoparticles<sup>48</sup>

## Safety considerations when handling metal powders

Table VII

### Exposure limits for tantalum dust<sup>35,53</sup>

Agency/country	TWA (mg/m <sup>3</sup> )	STEL (mg/m <sup>3</sup> )	Other (mg/m <sup>3</sup> )
ACGIH	5		
NIOSH	5	10	
OSHA	5		
Canada	5	10	
Austria	5	10	
Belgium	5		
Denmark	5		
Finland			10 (in 8 h)
Germany	10 (inhaleable), 3 (respirable)		
Ireland	10 (inhaleable), 4 (respirable)		
Italy	5		
Netherlands	10 (inhaleable), 5 (respirable)		
Norway	10 (total dust), 5 (respirable)		
Spain			5 (VLA)
Sweden	10 (total dust), 5 (respirable)		
UK OES	5	10	

VLA: Valore Limite Ambientales (Environmental Limit Value)

### Hafnium

As far as is known, the chemical, physical, and toxicological properties of hafnium metal have not been thoroughly investigated. Hafnium is a poison by unspecified route, but due to its low solubility in water it is not absorbed efficiently by ingestion. However many hafnium compounds are known to be poisonous<sup>54</sup>.

The following effects of exposure to hafnium have been noted<sup>37</sup>:

- Toxic by inhalation and may cause irritation to the nose, throat and mucous membranes
- May cause irritation to the skin
- May cause irritation to the eyes
- May cause damage to the liver.

The exposure limits are given in Table VIII.

### Niobium

The following effects have been reported<sup>55</sup>:

- On inhalation it may cause irritation of the mucous membranes. Inhaled particles may be retained in the lungs
- Metallic niobium has a low order of toxicity due to poor absorption from stomach and intestines
- May cause irritation to the skin
- May cause transient, mechanical irritation to the eyes. Chronic eye exposure may cause conjunctivitis
- Niobium crosses the placental barrier in animals.

Niobium, when inhaled, is retained mainly in the lungs, and secondarily in bones. It interferes with calcium as an activator of enzyme systems<sup>56</sup>.

Table VIII

### Exposure limits for hafnium dust<sup>54</sup>

Agency	TWA (mg/m <sup>3</sup> )	STEL (mg/m <sup>3</sup> )
NIOSH	5	10
OSHA	5	

The TWA and STEL values have not been set but there is an occupational exposure limit<sup>55</sup> of 15 mg/m<sup>3</sup>.

### Prevention of potential risks

There are four general principles that should guide the setting of procedures to prevent or at least minimize the fire/explosion and health risks (adapted from<sup>57-59</sup>). These are discussed in the following sections.

#### Prevent the suspension of powder particles in the air

- Ideally, work should be conducted in an oxygen-free atmosphere (i.e. glove box etc.)
- When this is not possible, handling should be done with great care and within the working zone of a suitable dust-extraction system to prevent any fugitive dust from settling within the facility
- Special care must be taken when cleaning equipment, bench tops, etc. and particularly if an accidental spill occurs. No compressed air hoses should be used
- The dust extraction or venting system must be designed to convey powders at concentrations below their MEC.

#### Eliminate all sources of ignition in powder-handling areas

- No smoking or smoking materials, including lighters or matches, should be allowed in areas where powder or dust is present
- No flame, spark-producing or propellant-actuated tools or activities should be carried out in an area where a powder is present
- Locate electric motors and as much electrical equipment as possible outside the processing areas
- Ensure that there are no hot surfaces (e.g. heating pads, hotplates etc.) in the powder-handling area
- Conductive and non-sparking tools must be used for handling and cleaning
- Bonding and grounding of machinery must be done to prevent static electricity buildup

# Safety considerations when handling metal powders

*Table IX*  
**Typical static electrical energies in non-earthed items<sup>60</sup>**

Charged object	Capacitance (pF)	Potential (kV)	Energy (mJ)
Single screw	1	5	0.01
Flange width = 100 mm	10	10	0.5
Shovel	20	15	2
Small container (~50 litres)	50	8	2
Funnel	50	15	6
Person	300	10	25-30
Drum (200 litres)	200	20	40
Road tanker	1 000	15	100

- All moveable equipment, such as drums, containers, and scoops must be bonded and grounded during powder transfer by the use of clips and flexible ground leads
- Personnel should also be grounded when working with powders, and the flooring in a facility should be suitably surfaced to minimize charge buildup
- During transfer, powder must not be poured or slid on nonconductive surfaces
- Work clothing should be made of smooth, hard-finished, closely woven fire resistant/fire retardant fabrics which tend not to accumulate static electric charges.

The static charge buildup from even small objects can be sufficient to ignite an explosion of fine powders. Table IX shows the typical static charge energies that can be generated for various items.

The European Standard EN 1127-1 lists the common ignition sources that have resulted in explosions or fires (Table X)<sup>61</sup>.

### Limit the size of the fire or explosion

- There should be regular cleaning of the laboratory and equipment to prevent any buildup of dust
- Work with the minimum amount of powder that is needed
- Ensure powder containers are closed immediately after use
- Store all containers (sealed) in a room separate from the handling areas. This room must comply with the necessary requirements for fire-proof storage. Long-term storage should be in argon-filled steel drums with

tightly fitting clamp-on sealable lids. The metal powder should not be stored in areas containing flammable liquids or other combustible materials, due to the differences in fire-fighting methods

- Have fireproof containers readily available for disposal of any spilled or burning powders
- There should be no false ceilings or difficult-to-access sections (e.g. cabling conduits etc.) in the working or storage areas where dust could collect unnoticed
- The dust extraction system must also be cleaned and maintained on a regular basis
- The clothing worn by workers should not have exposed cuffs, turn-ups, or pockets or other features where dust might accumulate.

The US National Fire Protection Agency (NFPA) specifies immediate cleaning when a dust layer exceeds 0.4 mm (1/64 inch) over at least 5 per cent of the facility area (this includes the floor, overhead structures, equipment, counters etc.)<sup>62</sup>. While this may be difficult to implement, it certainly emphasizes the seriousness of the potential risk.

### Protect personnel from exposure

There must be provision of suitable clothing and equipment to protect personnel while working in a powder handling and processing area. These should include:

- respirators (with correct filters)
- chemically resistant and fire-retardant laboratory coats/overalls
- gloves (both for fire protection but also to prevent skin contact)
- safety glasses/face shields with hair/head protection.

These should remain in the working area to prevent carry-over of dust to other areas (offices etc.). Suitable storage and changing facilities would be required.

A programme of regular inspection, cleaning, replacement of filters, laundry of clothing etc. should be instituted.

Before leaving the facility, personnel should be required to wash their hands and faces and any other exposed areas to remove any powder residues.

### Fire fighting procedures

Detailed procedures that are suitable for a particular facility should be sought from professional firefighters. However the following guidelines provide a starting point:

- It is extremely important that, should a fire start, there is a rapid response to deal with it as this can quickly escalate in intensity.

*Table X*  
**Possible ignition sources, as listed in EN 1127-1<sup>61</sup>**

Hot surfaces
Flames and hot gases (including hot particles)
Mechanically generated sparks
Electrical apparatus
Stray electrical currents, cathodic corrosion protection
Static electricity
Lightning
Radio frequency (RF) electromagnetic waves from 104 Hz to 3x10 <sup>12</sup> Hz
Electromagnetic waves from 3 x 10 <sup>11</sup> Hz to 3 x 10 <sup>15</sup> Hz
Ionising radiation
Ultrasonics
Adiabatic compression and shock waves
Chemical reactions, including self-ignition of dusts

# Safety considerations when handling metal powders

Table XI

Fire-extinguishing agents to be used on metal powder fires<sup>23</sup>

Extinguishing Agents	Metals								
	Alkali Metals (Calcium, NaK, Sodium)	Lithium	Aluminum	Iron and Steel	Magnesium	Niobium	Tantalum	Titanium	Zirconium
Coke (carbon microspheroids)	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes
Met-L-X	Yes*	No	Yes*	Yes	Yes*	Yes*	Yes*	Yes*	Yes*
Lith-X	Yes*	Yes*	No	No	No	No	No	No	No
Copper powder	Yes*	Yes*	Yes	No	No	No	No	No	No
Dry flux	Yes	Yes	Yes*	No	Yes*	No	No	No	No
Dry sand	Yes	Yes	Yes*	Yes	Yes*	Yes*	Yes*	Yes*	Yes*
Dry lithium chloride	Yes	Yes	No	No	No	No	No	Yes	Yes
Dry soda ash	Yes	Yes	Yes	No	Yes	No	No	Yes	Yes
Dry sodium chloride	Yes	Yes	Yes*	No	Yes*	Yes*	Yes*	Yes*	Yes*
Water	No	No	No	Yes	No	No	No	No	No
Foam	No	No	No <sup>†</sup>	Yes	No	No	No	No	No
Argon	Yes*	Yes	Yes*	Yes	Yes*	Yes*	Yes*	Yes*	Yes*
CO <sub>2</sub>	No	No	No	No	No	No	No	No	No
Nitrogen	Yes*	No	No	Yes	No	No	No	No	No
Halon	No	No	No	No	No	No	No	No	No
Halon replacements	No	No	No	No	No	No	No	No	No

Note: When combustible metals are blended with other materials, the extinguishing agent should be compatible with the combustible metal.

\*Preferred extinguishing agent.

<sup>†</sup>Aqueous film forming foam (AFFF) has been shown to be effective on aluminum paste fires in the incipient stage where a Class B solvent is the primary fuel.




Figure 20—A summary of the approach to preventing dust explosions (redrawn from reference<sup>12</sup>)

## Safety considerations when handling metal powders

Table XII

### Standards for prevention of combustible dust fires and explosions

NFPA 654	Standard for the prevention of fire and dust explosions from the manufacturing, processing, and handling of combustible particulate solids
NFPA 484	Standard for combustible metals
NFPA 499	Recommended practice for the classification of combustible dusts and of hazardous (classified) locations for electrical installations in chemical process areas
NFPA 68	Standard on explosion protection by deflagration venting
AS/NZS 4745:2004	Code of practice for handling combustible dusts
SANS 60079-0	Explosive atmospheres—Part 0: equipment—general requirements
SANS 60079-10-2	Explosive atmospheres Part 10-2: classification of areas—combustible dust atmospheres
SANS 60079-17	Explosive atmospheres—Part 17: electrical installations inspection and maintenance
AS/NZS 2381.1:2005	Electrical equipment for explosive gas atmospheres—selection, installation and maintenance—general requirements
AS/NZS 61241.10:2005	Electrical apparatus for use in the presence of combustible dust—classification of areas where combustible dusts are or may be present
AS/NZS 1020:1995 SANS 10123	The control of undesirable static electricity
AS 1940-2004	The storage and handling of flammable and combustible liquids
AS/NZS 3833:2007	The storage and handling of mixed classes of dangerous goods, in packages and intermediate bulk containers
SANS 61241-4	Electrical apparatus for use in the presence of combustible dust—Part 4: Type of protection "pD"
SANS 10108	The classification of hazardous locations and the selection of apparatus for use in such locations

NFPA: National Fire Protection Agency<sup>63</sup>

AS/NZS: Australian/New Zealand Standards<sup>64</sup>

SANS: South African National Standards<sup>65</sup>

- The burning powder should if possible be deposited into a suitable fire-proof container (appropriate non-sparking shovels etc must be available)
- If this is not feasible, then the correct extinguishant must be used (see Table XI). These must be kept close at hand and personnel should be trained in their use
- Once the fire has been dealt with to the best of their ability, personnel should leave the area after turning off equipment and closing any doors
- Trained firefighters should then ensure that the fire is adequately dealt with and the area is safe for cleanup operations to take place
- Care must be taken to thoroughly and safely clean the facility and personnel must wear protective equipment. The debris must also be collected and stored in a suitable container for appropriate disposal.

### Conclusions

This paper has attempted to give an overview of the potential hazards that can arise when working with metal powders in general, but also with special reference to zirconium, tantalum, hafnium, and niobium.

There are well-established methods to characterize powders for their explosive potential and to provide limits for safe operation. These can be used to help establish and maintain a safe working environment.

The steps to characterize the potential risk as well as to prevent an explosion are summarized in Figure 20.

The impact of powders on health is difficult to quantify and it would be best to err on the side of caution by preventing exposure, as far as possible. This can be effectively achieved by the provision of suitable protective equipment as well as having properly designed venting systems installed.

Educating personnel on the risks and safe working procedures is also vitally important to avoid the occurrence of an explosive dust accident.

Table XII lists some pertinent standards relating to the prevention of metal powder fires and explosions.

### References

1. Investigation Report, Combustible Dust Hazard Study, November 2006, accessed at: [www.csb.gov/assets/document/Dust\\_Final\\_Report\\_Website\\_11-17-06.pdf](http://www.csb.gov/assets/document/Dust_Final_Report_Website_11-17-06.pdf).
2. Combustible Dust Policy Institute. <http://dustexplosions.blogspot.com/2011/01/legislators-more-regulation-is-comdust.html>
3. US Chemical Safety Board website, [www.csb.gov/investigations/investigations.aspx?Type=1&F\\_All=y](http://www.csb.gov/investigations/investigations.aspx?Type=1&F_All=y).
4. HOUGHT, J. [www.baghouse.com/2011/03/09/one-dust-explosion-per-week-in-uk-and-2000-per-year-in-europe-says-new-study/](http://www.baghouse.com/2011/03/09/one-dust-explosion-per-week-in-uk-and-2000-per-year-in-europe-says-new-study/)
5. PECKHAM, M. <http://techland.time.com/2011/05/24/combustible-dust-plant-explosion-may-cost-apple-500000-ipads/#ixzz1PKNoxPQD>
6. US Chemical Safety Board report number 2004-01-I-IN: Aluminium Dust Explosion, [www.csb.gov/assets/document/Hayes\\_Report.pdf](http://www.csb.gov/assets/document/Hayes_Report.pdf).
7. OSTIGUY, C., SOUCY, B., LAPOINTE, G., WOODS, C., MÉNARD, L., and TROTTIER, M. *Health Effects of Nanoparticles*, IRSST Report R-589, Second Edition, [www.irsst.qc.ca/media/documents/PubIRSST/R-589.pdf](http://www.irsst.qc.ca/media/documents/PubIRSST/R-589.pdf)
8. Industrial Fire Prevention web-site, <http://industrialfireprevention.blogspot.com/2010/04/fire-triangle-and-fire-tetrahedron.html>.
9. CHOLIN, J.M. <http://www.oshainfo.gatech.edu/DustExplosions.pdf>
10. CASHDOLLAR, K.L. *Journal of Loss Prevention in the Process Industries*, vol. 13, 2000. pp. 183–199.
11. DREIZIN, E. *Progress in Energy and Combustion Science*, vol. 35, 2009. pp. 141–167.
12. ECKHOFF, R.K. *Dust Explosions in the Process Industries*, Third Edition, Gulf Professional Publishing, ISBN 0-7506-7602-7.
13. The Office of Health, Safety and Security, <http://homer.ornl.gov/nuclearsafety/ns/techstds/standard/hdbk1081/hbk1081d.html>
14. HERTZBERG, M., ZLOCHOWER, I.A., and CASHDOLLAR, K.L. *Metal Dust Combustion: Explosion Limits, Pressures and Temperatures*, Twenty Fourth Symposium (International) on Combustion, The Combustion Institute, 1992. pp. 1827–1835.
15. ASTM International, ASTM E2651 - 10 Standard Guide for Powder Particle Size Analysis, <http://www.astm.org/Standard/index.shtml>.

## Safety considerations when handling metal powders

16. ASTM International, ASTM E1515 - 07 Standard Test Method for Minimum Explosible Concentration of Combustible Dusts, <http://www.astm.org/Standard/index.shtml>.
17. ASTM International, ASTM E2019 - 03(2007) Standard Test Method for Minimum Ignition Energy of a Dust Cloud in Air, <http://www.astm.org/Standard/index.shtml>.
18. ASTM International, ASTM E2021 - 09 Standard Test Method for Hot-Surface Ignition Temperature of Dust Layers, <http://www.astm.org/Standard/index.shtml>.
19. ASTM International, ASTM E1491 - 06 Standard Test Method for Minimum Auto-ignition Temperature of Dust Clouds, <http://www.astm.org/Standard/index.shtml>.
20. ASTM International, ASTM E1226 - 10 Standard Test Method for Explosibility of Dust Clouds, <http://www.astm.org/Standard/index.shtml>.
21. DUFAUD, O., TRAORE', M., PERRIN, L., CHAZELET, S., and THOMAS, D. *Experimental investigation and modelling of aluminium dusts explosions in the 20 L sphere*, Journal of Loss Prevention in the Process Industries, vol. 23, 2010. pp. 226–236.
22. BOUILLARD, J., VIGNES, A., DUFAUD, O., PERRIN, L., and THOMAS, D. *Ignition and explosion risks of nanopowders*, Journal of Hazardous Materials, vol. 181, 2010. pp. 873–880.
23. US National Fire Protection Association, NFPA 484: Standard for Combustible Metals, 2009, [www.nfpa.org](http://www.nfpa.org).
24. CASHDOLLAR, K.L. and ZLOCHOWER, I.A. *Explosion Temperatures of Metals and Other Elemental Dust Clouds*, Proceedings of the Sixth International Symposium on Hazards, Prevention, and Mitigation of Industrial Explosions (Halifax, NS, Canada, Aug. 27 - Sept. 1, 2006). pp. 98–113 <http://www.cdc.gov/niosh/mining/pubs/pdfs/etoma.pdf>.
25. Chemetall, *Precautionary Handling Advice for Zirconium, Zirconium Hydride, Titanium, Titanium Hydride and Zr/Ni- Alloys in Powder Form*, April 2010, [http://www.specialmetals.chemetall.com/pdf/AOEC7C3FC93C0CAC125771\\_F0025346F\\_0.pdf](http://www.specialmetals.chemetall.com/pdf/AOEC7C3FC93C0CAC125771_F0025346F_0.pdf).
26. LI, Q., LIN, B., LI, W., ZHAI, C., and ZHU, C. *Explosion characteristics of nano-aluminum powder-air mixtures in 20 L spherical vessels*, Powder Technology vol. 212, iss. 2, 10 October 2011. pp. 303–309.
27. RANDEBERG, E. and ECKHOFF, R.K. *Measurement of minimum ignition energies of dust clouds in the <1 mJ region*, Journal of Hazardous Materials, vol. 140, 2007. pp. 237–244.
28. OSHA, [http://www.wmma.org/wood-industry-resources/nep\\_combustible\\_dust.pdf](http://www.wmma.org/wood-industry-resources/nep_combustible_dust.pdf).
29. Crohmiq. <http://crohmiq.com/mie-fibc-minimum-ignition-energy-antistatic-big-bags.html>
30. OSHS. <http://www.osh.dol.govt.nz/order/catalogue/archive/static-electricity.pdf>
31. MATSUDA, T. and YAMAGUMA, M. *Tantalum dust deflagration in a bag filter dust-collecting device*, Journal of Hazardous Materials, vol. 77, 2000. pp. 33–42.
32. WU, H-C., CHANG, R-C., and HSIAO, H-C. *Research of minimum ignition energy for nano Titanium powder and nano Iron powder*, Journal of Loss Prevention in the Process Industries, vol. 22, iss. 1, January 2009. pp. 21–24.
33. Chemetall. [www.specialmetals.chemetall.com/pdf/Zirconium\\_metal\\_powde\\_AB\\_dry.pdf](http://www.specialmetals.chemetall.com/pdf/Zirconium_metal_powde_AB_dry.pdf)
34. ESPI Metals. <http://www.espi-metals.com/msds/Zirconium.htm>
35. Centres for Disease Control and Prevention. <http://www.cdc.gov/niosh/npg/npgd0585.html>
36. Atlantic Equipment Engineers. <http://micronmetals.thomasnet.com/Asset/HF-101-MSDS.doc>
37. ESPI Metals. <https://www.utdallas.edu/research/cleanroom/safety/msds/documents/hafnium.pdf>.
38. Tico Titanium. [http://www.ticotitanium.com/wp-content/themes/tico/pdfs/MSDS\\_Niobium\\_Base\\_Alloys\\_Solids.pdf](http://www.ticotitanium.com/wp-content/themes/tico/pdfs/MSDS_Niobium_Base_Alloys_Solids.pdf).
39. Canadian Centre for Occupational Health and Safety. [http://www.ccohs.ca/oshanswers/chemicals/chem\\_profiles/aluminum\\_powder/working\\_alu.html](http://www.ccohs.ca/oshanswers/chemicals/chem_profiles/aluminum_powder/working_alu.html)
40. HUANG, Y., RISHA, G.A., YANG, V., and YETTER, R.A. *Effect of particle size on combustion of aluminum particle dust in air*, Combustion and Flame, vol. 156, iss. 1, January 2009. pp. 5–13.
41. ABBASI, T. and ABBASI, S.A. *Dust explosions—Cases, causes, consequences, and control*, Journal of Hazardous Materials, vol. 140, 2007. pp. 7–44.
42. MATSUDA, T., YASHIMA, M., NIFUKU, M., and ENOMOTO, H. *Some aspects in testing and assessment of metal dust explosions*, Journal of Loss Prevention in the Process Industries, vol. 14, 2001. pp. 449–453.
43. Eastern Research Group, Inc., July 2011, [http://www.osha.gov/dsg/combustible\\_dust/expert\\_forum\\_summary\\_report.pdf](http://www.osha.gov/dsg/combustible_dust/expert_forum_summary_report.pdf).
44. CADWALLADER, L.C. *Dust Combustion Safety Issues for Fusion Applications*, Idaho National Engineering and Environmental Laboratory, Bechtel BWXT, Idaho, LLC, May 2003. <http://www.inl.gov/technicalpublications/Documents/2699859.pdf>
45. OSHA. [www.osha.gov/SLTC/healthguidelines/hafnium/recognition.html](http://www.osha.gov/SLTC/healthguidelines/hafnium/recognition.html)
46. DASTIDAR, A.G., AMYOTTE, P.R., GOING, J., and CHATRATHI, K. *Flammability limits of dusts: Minimum inerting concentrations*, Process Safety Progress, vol. 18, no. 1, 1999. pp. 56–63.
47. McCLELLAN, G., RODRIGUEZ, J., and MILLAGE, K. <http://www.dtic.mil/ndia/2007cbis/wednesday/mcclellanWed1130.pdf>
48. BUZEA, C., PACHEO, I., and ROBBIE, K. *Nanomaterials and nanoparticles: Sources and toxicity*, Biointerphases, vol. 2, iss. 4, 2007. pp. MR17–MR172. <http://arxiv.org/ftp/arxiv/papers/0801/0801.3280.pdf>.
49. Centres for Disease Control and Prevention. <http://www.cdc.gov/niosh/npg/npgd0677.html>
50. <http://en.wikipedia.org/wiki/Zirconium>.
51. Centres for Disease Control and Prevention. <http://www.cdc.gov/niosh/idlh/7440677.html>
52. KERWIEN, S.C. *Toxicity of tungsten, molybdenum, and tantalum and the environmental and occupational laws associated with their manufacture, use, and disposal*. <http://www.dtic.mil/cgi-bin/GetTRDoc?AD=ADA310298&Location=U2&doc=GetTRDoc.pdf>.
53. Cabot Corporation. <http://www.cabot-corp.com/wcm/msds/en-gb/TA/TANTALUM-EUR-EN.pdf>.
54. Centres for Disease Control and Prevention. <http://www.cdc.gov/niosh/npg/npgd0309.html>.
55. ESPI Metals. <http://www.espi-metals.com/msds/s/niobium.htm>.
56. Lenntech. <http://www.lenntech.com/periodic/elements/nb.htm#ixzz1REOn7nj1>.
57. The Aluminum Association. Recommendations for storage and handling of aluminium powders and paste, 4th edition, 2006.
58. POULSEN, E. [www.titanium.org/files/ItemFileA4631.pdf](http://www.titanium.org/files/ItemFileA4631.pdf)
59. POULSEN, E. *Safety-Related Problems in the Titanium Industry in the Last 50 Years*, JOM, vol. 52, no. 5, 2000. pp. 13–17.
60. ECKHOFF, R.K. and RANDEBERG, E. *Journal of Loss Prevention in the Process Industries*, vol. 20, iss. 4–6, July–November 2007. pp. 396–401.
61. European Standard. EN 1127-1 'Explosive atmospheres – Explosion prevention and protection – Part 1: Basic concepts and methodology', 2007.
62. US National Fire Protection Association. NFPA 654: Standard for the Prevention of Fire and Dust Explosions from the Manufacturing, Processing, and Handling of Combustible Particulate Solids, [www.nfpa.org](http://www.nfpa.org).
63. National Fire Protection Agency, <http://www.nfpa.org/>
64. Australian/New Zealand Standards, <http://www.standards.org.au/>
65. South African National Standards, <https://www.sabs.co.za/> ◆