

Spherical void formers in concrete slabs

C C Marais, J M Robberts, B W J van Rensburg

ERRATA

JOURNAL OF THE SOUTH AFRICAN
INSTITUTION OF CIVIL ENGINEERING

Vol 53 No 1, April 2011, Page 63, Paper 738

Publication particulars of paper being corrected:
Vol 52 (2) 2010, pp 2-11, Paper 738

ERRATA

An error appeared in Figure 11 on page 10.

The correct figure looks as follows:




Figure 11 Cost comparison of SVF, coffer and post-tensioned slabs in South Africa for a distributed 2,5 kPa additional dead load and 2,5 kPa live load